



| XPZ | | | |
|----------------|--------------|----------------|--------------|
| Belt reference | Datum length | Belt reference | Datum length |
| ISO | mm ISO | ISO | mm ISO |
| XPZ 630 | 630 | XPZ 1512 | 1512 |
| XPZ 637 | 637 | XPZ 1520 | 1520 |
| XPZ 662 | 662 | XPZ 1537 | 1537 |
| XPZ 670 | 670 | XPZ 1550 | 1550 |
| XPZ 687 | 687 | XPZ 1587 | 1587 |
| XPZ 710 | 710 | XPZ 1600 | 1600 |
| XPZ 722 | 722 | XPZ 1650 | 1650 |
| XPZ 730 | 730 | XPZ 1687 | 1687 |
| XPZ 737 | 737 | XPZ 1700 | 1700 |
| XPZ 750 | 750 | XPZ 1750 | 1750 |
| XPZ 760 | 760 | XPZ 1800 | 1800 |
| XPZ 762 | 762 | XPZ 1850 | 1850 |
| XPZ 772 | 772 | XPZ 1900 | 1900 |
| XPZ 787 | 787 | XPZ 1950 | 1950 |
| XPZ 800 | 800 | XPZ 2000 | 2000 |
| XPZ 812 | 812 | XPZ 2030 | 2030 |
| XPZ 837 | 837 | XPZ 2120 | 2120 |
| XPZ 850 | 850 | XPZ 2160 | 2160 |
| XPZ 862 | 862 | XPZ 2240 | 2240 |
| XPZ 875 | 875 | XPZ 2280 | 2280 |
| XPZ 887 | 887 | XPZ 2360 | 2360 |
| XPZ 900 | 900 | XPZ 2410 | 2410 |
| XPZ 912 | 912 | XPZ 2500 | 2500 |
| XPZ 925 | 925 | XPZ 2540 | 2540 |
| XPZ 937 | 937 | XPZ 2650 | 2650 |
| XPZ 950 | 950 | XPZ 2690 | 2690 |
| XPZ 962 | 962 | XPZ 2800 | 2800 |
| XPZ 975 | 975 | XPZ 2840 | 2840 |
| XPZ 980 | 980 | XPZ 3000 | 3000 |
| XPZ 987 | 987 | XPZ 3150 | 3150 |
| XPZ 1000 | 1000 | XPZ 3350 | 3350 |
| XPZ 1010 | 1010 | XPZ 3550 | 3550 |
| XPZ 1012 | 1012 | | |
| XPZ 1030 | 1030 | | |
| XPZ 1037 | 1037 | | |
| XPZ 1060 | 1060 | | |
| XPZ 1062 | 1062 | | |
| XPZ 1077 | 1077 | | |
| XPZ 1080 | 1080 | | |
| XPZ 1087 | 1087 | | |
| XPZ 1090 | 1090 | | |
| XPZ 1112 | 1112 | | |
| XPZ 1120 | 1120 | | |
| XPZ 1137 | 1137 | | |
| XPZ 1140 | 1140 | | |
| XPZ 1150 | 1150 | | |
| XPZ 1162 | 1162 | | |
| XPZ 1180 | 1180 | | |
| XPZ 1187 | 1187 | | |
| XPZ 1200 | 1200 | | |
| XPZ 1202 | 1202 | | |
| XPZ 1212 | 1212 | | |
| XPZ 1237 | 1237 | | |
| XPZ 1250 | 1250 | | |
| XPZ 1262 | 1262 | | |
| XPZ 1270 | 1270 | | |
| XPZ 1280 | 1280 | | |
| XPZ 1285 | 1285 | | |
| XPZ 1287 | 1287 | | |
| XPZ 1312 | 1312 | | |
| XPZ 1320 | 1320 | | |
| XPZ 1337 | 1337 | | |
| XPZ 1340 | 1340 | | |
| XPZ 1362 | 1362 | | |
| XPZ 1400 | 1400 | | |
| XPZ 1412 | 1412 | | |
| XPZ 1420 | 1420 | | |
| XPZ 1450 | 1450 | | |
| XPZ 1487 | 1487 | | |
| XPZ 1500 | 1500 | | |

| XPA | | | |
|----------------|--------------|----------------|--------------|
| Belt reference | Datum length | Belt reference | Datum length |
| ISO | mm ISO | ISO | mm ISO |
| XPA 747 | 747 | XPA 2360 | 2360 |
| XPA 757 | 757 | XPA 2430 | 2430 |
| XPA 782 | 782 | XPA 2500 | 2500 |
| XPA 800 | 800 | XPA 2650 | 2650 |
| XPA 832 | 832 | XPA 2800 | 2800 |
| XPA 850 | 850 | XPA 3000 | 3000 |
| XPA 857 | 857 | XPA 3150 | 3150 |
| XPA 882 | 882 | XPA 3350 | 3350 |
| XPA 900 | 900 | XPA 3550 | 3550 |
| XPA 907 | 907 | XPA 3750 | 3750 |
| XPA 925 | 925 | XPA 4000 | 4000 |
| XPA 932 | 932 | | |
| XPA 950 | 950 | | |
| XPA 957 | 957 | | |
| XPA 975 | 975 | | |
| XPA 982 | 982 | | |
| XPA 1000 | 1000 | | |
| XPA 1007 | 1007 | | |
| XPA 1030 | 1030 | | |
| XPA 1060 | 1060 | | |
| XPA 1082 | 1082 | | |
| XPA 1090 | 1090 | | |
| XPA 1107 | 1107 | | |
| XPA 1120 | 1120 | | |
| XPA 1140 | 1140 | | |
| XPA 1150 | 1150 | | |
| XPA 1157 | 1157 | | |
| XPA 1180 | 1180 | | |
| XPA 1207 | 1207 | | |
| XPA 1215 | 1215 | | |
| XPA 1232 | 1232 | | |
| XPA 1250 | 1250 | | |
| XPA 1257 | 1257 | | |
| XPA 1282 | 1282 | | |
| XPA 1285 | 1285 | | |
| XPA 1307 | 1307 | | |
| XPA 1320 | 1320 | | |
| XPA 1332 | 1332 | | |
| XPA 1357 | 1357 | | |
| XPA 1360 | 1360 | | |
| XPA 1400 | 1400 | | |
| XPA 1450 | 1450 | | |
| XPA 1482 | 1482 | | |
| XPA 1500 | 1500 | | |
| XPA 1507 | 1507 | | |
| XPA 1532 | 1532 | | |
| XPA 1550 | 1550 | | |
| XPA 1582 | 1582 | | |
| XPA 1600 | 1600 | | |
| XPA 1650 | 1650 | | |
| XPA 1700 | 1700 | | |
| XPA 1750 | 1750 | | |
| XPA 1800 | 1800 | | |
| XPA 1850 | 1850 | | |
| XPA 1900 | 1900 | | |
| XPA 1950 | 1950 | | |
| XPA 2000 | 2000 | | |
| XPA 2060 | 2060 | | |
| XPA 2120 | 2120 | | |
| XPA 2240 | 2240 | | |

| XPB | |
|----------------|--------------|
| Belt reference | Datum length |
| ISO | mm ISO |
| XPB 1250 | 1250 |
| XPB 1260 | 1260 |
| XPB 1320 | 1320 |
| XPB 1340 | 1340 |
| XPB 1400 | 1400 |
| XPB 1410 | 1410 |
| XPB 1450 | 1450 |
| XPB 1500 | 1500 |
| XPB 1510 | 1510 |
| XPB 1550 | 1550 |
| XPB 1590 | 1590 |
| XPB 1600 | 1600 |
| XPB 1650 | 1650 |
| XPB 1690 | 1690 |
| XPB 1700 | 1700 |
| XPB 1750 | 1750 |
| XPB 1800 | 1800 |
| XPB 1850 | 1850 |
| XPB 1900 | 1900 |
| XPB 1950 | 1950 |
| XPB 2000 | 2000 |
| XPB 2020 | 2020 |
| XPB 2120 | 2120 |
| XPB 2150 | 2150 |
| XPB 2240 | 2240 |
| XPB 2280 | 2280 |
| XPB 2360 | 2360 |
| XPB 2410 | 2410 |
| XPB 2500 | 2500 |
| XPB 2530 | 2530 |
| XPB 2650 | 2650 |
| XPB 2680 | 2680 |
| XPB 2800 | 2800 |
| XPB 2840 | 2840 |
| XPB 2990 | 2990 |
| XPB 3000 | 3000 |
| XPB 3150 | 3150 |
| XPB 3350 | 3350 |
| XPB 3550 | 3550 |
| XPB 3750 | 3750 |
| XPB 4000 | 4000 |
| XPB 4250 | 4250 |
| XPB 4500 | 4500 |
| XPB 4750 | 4750 |

| XPC | |
|----------------|--------------|
| Belt reference | Datum length |
| ISO | mm ISO |
| XPC 2000 | 2000 |
| XPC 2120 | 2120 |
| XPC 2240 | 2240 |
| XPC 2360 | 2360 |
| XPC 2500 | 2500 |
| XPC 2650 | 2650 |
| XPC 2800 | 2800 |
| XPC 3000 | 3000 |
| XPC 3150 | 3150 |
| XPC 3350 | 3350 |
| XPC 3550 | 3550 |
| XPC 3750 | 3750 |
| XPC 4000 | 4000 |
| XPC 4250 | 4250 |
| XPC 4500 | 4500 |
| XPC 4750 | 4750 |

Quad-Power® II ordering code is composed as follows:

XPZ630

XPZ - Section
630 - Datum length (mm)

Dimensions in bold are available from stock.